

Field Handling Techniques

Epoxy-Coated Rebar

Material Receipt & Inspection

- Check for secure tie-downs on transport.
- Check for proper padding and bar separation.
- Visually inspect the epoxy-coated bars for damage.
- Check coating on sheared ends.
- Patch uncoated or partially coated sheared ends.
- Patch any other observed damage.
- Always use an approved patching system.

Truck Unloading & Job Site Handling

- Do not slide or skid bundles from truck bed to ground.
- Use power lift equipment.
- Use protective nylon slings or padded wire rope slings.
- Lift bundles at multiple pick-up points or
- Use a spreaderbar with additional nylon straps to prevent sags and bar-to-bar abrasion in longer bundles.
- Do not drag or drop bundles or individual bars.

Storage

- Schedule delivery to minimize long-term storage at job site.
- Store close to the area where they will be placed to keep handling operations to a minimum.
- If storage is expected, use opaque plastic sheeting to protect the epoxy-coated rebar from damage by ultraviolet rays.
- Store bundles above ground on timbers or other cribbing.
- Space support cribbing close enough together to prevent excessive sagging of the bundles.
- If protective sheeting is used, allow for adequate air circulation around the bars to minimize condensation.

Placement

- Handle carefully to prevent damage to coating.
- Use nylon slings or other padded material to lift bundles.
- Lift and set coated bar into place.
- Do not drag across the ground or deck.
- Minimize walking on epoxy-coated bars.
- Do not drop tools on the bars while placing.
- Visually inspect bars for damage after placement.
- Properly repair any damage.
- Protect bars tied in place from long exposure or severe environmental conditions.

Bar Supports & Tie Wire

- Metal bar supports must be coated with a non-corrosive, non-conductive material, i.e. epoxy, nylon or PVC.
- Support steel; i.e. spacers used with epoxy-coated bars must also be coated with a non-conductive material such as epoxy, nylon or PVC.
- Reinforcing bars used as bar supports must also be epoxy-coated.
- Epoxy-coated tie wire, 16.5 gauge+, must be used with epoxy-coated rebar.

Splicing & Coupling Devices

- Install coupling devices per manufacturer's requirements.
- Couplers should be pre-coated with fusion-bonded epoxy.
- Repair any coating damage on the couplers as needed.
- For welded splices, all welds and weld splice members must be coated with the same patching material used for other coated bar repairs on the project.
- When welding, coating damage to bars near the welded splices must be repaired.
- When welding epoxy-coated bars, appropriate protective mask must be worn, safety equipment used and suitable ventilation provided.

Field Cutting

- Field-cutting should be avoided and only permitted with specifier/owner approval.
- Repair of cut ends should utilize the same material that is used for repair of damaged epoxy-coated rebar.
- Saw-cutting is recommended to reduce coating damage.
- Use hydraulically powered cutters or friction cutting tools to minimize damage.
- Avoid flame-cutting, wear protective mask, repair promptly.

Final Inspection & Repair

- After epoxy-coated rebar is placed, make a final inspection to locate all damage.
- All visible damage must be repaired before the concrete is placed.
- Use approved epoxy repair material designed for specific climatic conditions.
- There is a timely four-step, two-part liquid repair; for more information refer to the Concrete Reinforcing Steel Institute's *Field Handling Techniques for Epoxy-Coated Rebar*, 1996.

Concrete Pour

- Use caution when walking on the rebar, do not drop any hand-tools or construction materials.
- Set-up runways for concrete buggies and pumping hoses, etc., and properly support them. Maneuver carefully to minimize damage to the coating and to prevent shifting of placed bars.
- Use rubber or non-metallic vibrator heads when compacting concrete to minimize damage on placed epoxy-coated bars. Metal heads can damage the epoxy coating on bars within poured concrete.

Source: Concrete Reinforcing Steel Institute

Hot-Dip Galvanized Rebar

- Visually inspect for damage.
- Check for secure tie-downs on transport.

- No special handling or care necessary.
- Lift bundles at multiple pick-up points or
- Use a spreader bar with additional nylon straps to prevent sags and bar-to-bar abrasion in longer bundles.

- Block material and store on a slant to allow for water drainage and air flow.

- No special care necessary.

- Bar supports, spacers and rebar supports should all be hot-dip galvanized.
- 16.5 gauge or heavier galvanized tie wire should be used.
- Other acceptable materials for these parts are plastic or non-conductive coated steel.

- A bar-lock coupler is recommended, either galvanized or stainless.
- For welded splices, all welds and weld splice members must be touched up as recommended in ASTM A 780.
- Use appropriate protective masks and suitable ventilation when welding.

- Field-cutting should be avoided.
- Repair of cut ends shall be done using touch-up procedures from ASTM A 780.

- Touch-up of cut and burned ends should be done following procedures recommended in ASTM A 780.

- No special handling or care necessary.

Source: American Galvanizers Association